


More properties effected

by the high water.







This picture shows that home owners  
which are high above the lake are  
effected by the high water.

The high water and the wave  
action has eroded the bank and created  
a land slide and destroyed  
the steps and footing. The home is  
right behind this and next in line.

